

Problems with the update of the engine control of the Mercedes Benz Sprinter 3 (906.633)




Affected

KTS product family with support for PassThru (e.g. KTS 350 / KTS 540 / KTS 560 / KTS 570 / KTS 590)

Error

When updating the engine control unit CDID3 (CDI) of the Mercedes Benz Sprinter 3 (906.633), aborts may occur.

 If an abort occurs during an update of the motor control unit, it may be necessary to replace the motor control unit.

Cause

The problem is being investigated.

Remedy

Until the investigation is completed, no update of the engine control unit CDID3 (CDI) of the Mercedes Benz Sprinter 3 (906.633) must be carried out!