

# Product Safety Recall

## Bosch Brake Disc Rotors

Designed for fitment on the front axle of selected Holden Colorado and Isuzu D-Max models manufactured from 2011

Part number 0986479V29

with manufacturing dates from January 2017 - August 2019 (numbers 717 - 956)



Ⓟ BOSCH 0 986 479 V29 MIN. TH. 25.0 (250) [25A] 853241591

Part Number: 0 986 479 V29



Manufacture code identification: 717 to 956



Numbers on packaging include:

0986479V29HWZ - 19348788 - ACDR2262 OR 0986479V298KW - BD2262

Sold from 1 March 2017

Distributed by Robert Bosch (Australia) Pty Ltd

**Defect:** Cracking of the brake disc rotor hub (Product) may occur in some instances where the wall thickness in the neck area is thinner than expected

**Hazard:** If the Product cracks the vehicle could experience reduced braking capacity which may increase the risk of an accident occurring

**What to do:** Consumers should stop using the potentially defective Product, including vehicles fitted with the Product. For vehicles fitted with the Product, consumers should return the vehicle to the vehicle dealer or to the store which fitted the Product. Products not fitted to a vehicle may be returned for a full refund

**Contact:** Robert Bosch (Australia) Pty Ltd on 1800 025 462, or email: BoschService.NetworkWebsiteEnquiry@au.bosch.com

See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information