


Cabin Filters

Installation Tips



Top European Vehicles



BOSCH
Invented for life

AUDI	
A3 [8V1]	<input type="radio"/> M 2540 <input checked="" type="radio"/> R 2543 <input checked="" type="radio"/> A 8530
10 Minutes In the glove compartment	
A4 [8K5, B8] Avant, A4 [8K2, B8], Q5 [8RB]	<input type="radio"/> M 5016 <input checked="" type="radio"/> R 2369 <input checked="" type="radio"/> A 8522
10 Minutes Under the glove compartment	
A4 [8E5, B6] Avant, A4 [8E2, B6]	<input type="radio"/> M 2071 <input checked="" type="radio"/> R 2371 <input checked="" type="radio"/> A 8513
10 Minutes Engine compartment	
A4 [8D5, B5] Avant, A4 [8ED, B7] Avant	<input type="radio"/> M 2017 <input checked="" type="radio"/> R 2317
10 Minutes Engine compartment	
Q7 [4LB]	<input type="radio"/> M 2114 <input checked="" type="radio"/> R 2431 <input checked="" type="radio"/> A 8517
15 Minutes Under the glove compartment	
BMW	
1 [E 87], 3 [E 90], 3 [E 91] Touring, X 1 [E 84]	<input type="radio"/> M 2124 <input checked="" type="radio"/> R 2424 <input checked="" type="radio"/> A 8508
10 Minutes Engine compartment	
3 [E 46], 3 [E 46] Touring, X 3 [E 83]	<input type="radio"/> M 2036 <input checked="" type="radio"/> R 2336
20 Minutes Engine compartment	
CHEVROLET	
Cruze [J300]	<input type="radio"/> M 2004 <input checked="" type="radio"/> R 2304 <input checked="" type="radio"/> A 8512
10 Minutes Under the glove compartment	
Niva	<input type="radio"/> M 2230
15 Minutes Engine compartment	
Aveo, Aveo [T255], Aveo [T250], Aveo [T200], Kalos [T200] Hatchback	<input type="radio"/> M 2241
20 Minutes Under the glove compartment	
Lacetti [J200], Nubira [J200] Wagon, Optra [J200] Hatchback, Optra [J200]	<input type="radio"/> M 2223
15 Minutes Under the glove compartment	
Matiz [M200], Spark [M200]	<input type="radio"/> M 2171
15 Minutes Under the glove compartment	
CITROËN	
C3 [A8], C4 [B5]	<input type="radio"/> M 2079 <input checked="" type="radio"/> R 2379 <input checked="" type="radio"/> A 8501
10 Minutes Engine compartment	
Berlingo [B9], C4 Grand Picasso [B58], C4 Picasso [B58]	<input type="radio"/> M 5026 <input checked="" type="radio"/> R 5522 <input checked="" type="radio"/> A 8510
15 Minutes Under the glove compartment	
C1 [B0]	<input type="radio"/> M 2189 <input checked="" type="radio"/> A 8552
5 Minutes In the glove compartment	
Jumper [U5]	<input type="radio"/> M 2042
20 Minutes Engine compartment	
Jumper [U9]	<input type="radio"/> M 2065 <input checked="" type="radio"/> R 5551
15 Minutes Engine compartment	
Saxo [S8]	<input type="radio"/> M 2154
5 Minutes Engine compartment	
C5 [X3]	<input type="radio"/> M 2112 <input checked="" type="radio"/> R 2412
5 Minutes Driver footwell	
DACIA	
Sandero II [B8]	<input type="radio"/> M 5011 <input checked="" type="radio"/> R 5031 <input checked="" type="radio"/> A 8540
10 Minutes Under the glove compartment	
FIAT	
Grande Punto [199], Punto Evo [199]	<input type="radio"/> M 2188 <input checked="" type="radio"/> R 2537 <input checked="" type="radio"/> A 8514
15 Minutes Under the glove compartment	
Punto '03 [188], Punto '03 [288] Van, Punto '99 [188], Punto '99 [288] Van	<input type="radio"/> M 2072 <input checked="" type="radio"/> R 2365
10 Minutes Under the glove compartment	
500 [312], Panda '12 [312], Ypsilon [312]	<input type="radio"/> M 5005 <input checked="" type="radio"/> R 5589 <input checked="" type="radio"/> A 8531
20 Minutes Under the glove compartment	
Croma '05 [194], Panda '03 [169]	<input type="radio"/> M 2076 <input checked="" type="radio"/> R 2376
15 Minutes Engine compartment	

Panda '03 [169], Ka '08 [JD]	<input type="radio"/> M 2106 <input checked="" type="radio"/> R 5583 <input checked="" type="radio"/> A 8541
15 Minutes Under the glove compartment	
500X [334], 500L [330]	<input type="radio"/> M 5017 <input checked="" type="radio"/> R 5548 <input checked="" type="radio"/> A 8542
10 Minutes Under the glove compartment	
Ducato '02 [244]	<input type="radio"/> M 2042
20 Minutes Engine compartment	
Ducato '14 [290], Ducato '06 [250], Ducato '11 [250]	<input type="radio"/> M 2065 <input checked="" type="radio"/> R 5551
15 Minutes Engine compartment	
FORD	
Fiesta '08 [JD, JH], Fiesta '13 [JA8, JR8], Fiesta '17 [JHH]	<input type="radio"/> M 2215 <input checked="" type="radio"/> R 2415 <input checked="" type="radio"/> A 8507
10 Minutes Passenger footwell	
Kuga '13 [DM2], Focus '15 [DY, BL], Turnier, C-MAX '11 [DXA], Focus '11 [DY, BL] Turnier, Focus '11 [DY, BK]	<input type="radio"/> M 5018 <input checked="" type="radio"/> R 2598 <input checked="" type="radio"/> A 8538
20 Minutes Under the gearshift	
Focus '08 [DA, HC], Focus '04 [DA3], Focus '04 [DA3] Turnier, Focus '08 [FF] Turnier, Focus '08 [FC]	<input type="radio"/> M 2113 <input checked="" type="radio"/> R 2413 <input checked="" type="radio"/> A 8536
20 Minutes Driver footwell	
Fusion '02 [JU], Fiesta '02 [JD, JH]	<input type="radio"/> M 2087 <input checked="" type="radio"/> R 2387
15 Minutes Driver footwell	
Focus '99 [DFW], Transit Connect '02, Focus '99 [DAW, DBW], Focus '99 [DNW] Turnier	<input type="radio"/> M 2045 <input checked="" type="radio"/> R 2345 <input checked="" type="radio"/> A 8516
10 Minutes Under the glove compartment	
HONDA	
Civic Hatchback [FK/FN]	<input type="radio"/> M 2203
10 Minutes Under the glove compartment	
HYUNDAI	
i20 [GB], i30 [GD], Elantra [MD, UD]	<input type="radio"/> M 5097
15 Minutes In the glove compartment	
i10 [IA], i10 [PA]	<input type="radio"/> M 2164
5 Minutes Under the glove compartment	
Solaris [RB], Solaris [RB] Hatchback	<input type="radio"/> M 5114
JEEP	
Renegade	<input type="radio"/> M 5017 <input checked="" type="radio"/> R 5548 <input checked="" type="radio"/> A 8542
10 Minutes Under the glove compartment	
KIA	
Cee'd [JD], Cee'd [JD] Sporty Wagon	<input type="radio"/> M 5097
15 Minutes In the glove compartment	
Optima [TF], Picanto [TA], Picanto [SA]	<input type="radio"/> M 2164
5 Minutes Under the glove compartment	
Rio [UB] Sedan, Rio [UB]	<input type="radio"/> M 5114
10 Minutes Under the glove compartment	
LADA	
Vesta	<input type="radio"/> M 5011 <input checked="" type="radio"/> R 5031 <input checked="" type="radio"/> A 8540
10 Minutes Under the glove compartment	
Granta [2190], Kalina, Kalina Hatchback, Kalina Kombi	<input type="radio"/> M 2230
15 Minutes Engine compartment	
LANCIA	
Ypsilon [843]	<input type="radio"/> M 2072 <input checked="" type="radio"/> R 2365
10 Minutes Under the glove compartment	
LEXUS	
RX [U3]	<input type="radio"/> M 2085 <input checked="" type="radio"/> R 2320
15 Minutes Under the glove compartment	
MERCEDES-BENZ	
B-Klasse [246], A-Klasse [176], GLA-Klasse [156]	<input checked="" type="radio"/> R 5505 <input checked="" type="radio"/> A 8545
10 Minutes Engine compartment	
C-Klasse [204] T-Modell, E-Klasse [212], GLK-Klasse [204], C-Klasse [204], E-Klasse [212] T-Modell	<input checked="" type="radio"/> R 5001 <input checked="" type="radio"/> A 8500
10 Minutes Engine compartment	
A-Klasse [169], B-Klasse [245]	<input checked="" type="radio"/> R 2410 <input checked="" type="radio"/> A 8520
5 Minutes Engine compartment	

Citan [415]	<input type="radio"/> M 2078 <input checked="" type="radio"/> A 8553
30 Minutes In the glove compartment	
MINI	
Mini [R 50], Mini [R 53], Mini [R 52] Cabrio	<input type="radio"/> M 2082 <input checked="" type="radio"/> R 2382
15 Minutes Under the glove compartment	
MITSUBISHI	
ASX [GA], Outlander [CW], Lancer [CY/CZ], Outlander [GF]	<input type="radio"/> M 2216 <input checked="" type="radio"/> R 2416
10 Minutes Under the glove compartment	
NISSAN	
Qashqai+2 [JJ10], Qashqai [J10], X-Trail [T31R], X-Trail [T31]	<input type="radio"/> M 2238 <input checked="" type="radio"/> R 5554 <input checked="" type="radio"/> A 8524
15 Minutes Under the glove compartment	
Qashqai [J11E]	<input type="radio"/> M 5057 <input checked="" type="radio"/> R 5562 <input checked="" type="radio"/> A 8546
10 Minutes In the glove compartment	
Juke [F15], Pulsar [C13]	<input type="radio"/> M 2247 <input checked="" type="radio"/> R 5574
25 Minutes Under the glove compartment	
Micra [K13K], Note [E12], Micra [K13KK], Sunny [N17K]	<input type="radio"/> M 2246
5 Minutes Under the glove compartment	
OPEL	
Corsa [D], Corsa [E]	<input type="radio"/> M 2188 <input checked="" type="radio"/> R 2537 <input checked="" type="radio"/> A 8514
15 Minutes Under the glove compartment	
Astra [J], Mokka, Meriva [B], Insignia [A] Sports Tourer	<input type="radio"/> M 2004 <input checked="" type="radio"/> R 2304 <input checked="" type="radio"/> A 8512
10 Minutes Under the glove compartment	
Combo [C], Vectra [C], Vectra [C] Caravan	<input type="radio"/> M 2076 <input checked="" type="radio"/> R 2376
15 Minutes Engine compartment	
Astra [H], Astra [H] GTC, Astra [G]	<input type="radio"/> M 2040 <input checked="" type="radio"/> R 5514 <input checked="" type="radio"/> A 8532
15 Minutes Under the glove compartment	
Astra [K]	<input checked="" type="radio"/> R 5575
20 Minutes In the glove compartment	
Astra [K] Sports Tourer	<input checked="" type="radio"/> R 5576
20 Minutes In the glove compartment	
Meriva [B]	<input checked="" type="radio"/> R 5577
20 Minutes In the glove compartment	
Mokka	<input checked="" type="radio"/> R 5578
20 Minutes In the glove compartment	
Vivaro [A]	<input type="radio"/> M 2208
10 Minutes Engine compartment	
PEUGEOT	
307 [T5], 307 [T5] Break/SW	<input type="radio"/> M 2079 <input checked="" type="radio"/> R 2379 <input checked="" type="radio"/> A 8501
10 Minutes Engine compartment	
208, 207 [A7], 207 [A7] CC, 2008 [A94], 207+	<input type="radio"/> M 2136 <input checked="" type="radio"/> R 2436 <input checked="" type="radio"/> A 8533
15 Minutes Engine compartment	
Partner [B9], 3008 [T8]	<input type="radio"/> M 5026 <input checked="" type="radio"/> R 5522 <input checked="" type="radio"/> A 8510
15 Minutes Under the glove compartment	
206 [T1], 206 [T1] CC, 206 [T1] SW, 206+ [T3E]	<input type="radio"/> M 2048 <input checked="" type="radio"/> R 2348 <input checked="" type="radio"/> A 8535
10 Minutes Engine compartment	
107 [B0]	<input type="radio"/> M 2189 <input checked="" type="radio"/> A 8552
5 Minutes In the glove compartment	
Boxer [U5], Boxer [U3]	<input type="radio"/> M 2042
20 Minutes Engine compartment	
Boxer [U9]	<input type="radio"/> M 2065 <input checked="" type="radio"/> R 5551
15 Minutes Engine compartment	
106 [S2], 106 [S1]	<input type="radio"/> M 2154
5 Minutes Engine compartment	
407 [D2], 407 [D2] SW, 407 [D2] Coupe	<input type="radio"/> M 2112 <input checked="" type="radio"/> R 2412
5 Minutes Driver footwell	
PORSCHE	
Macan [95B]	<input type="radio"/> M 5016 <input checked="" type="radio"/> R 2369 <input checked="" type="radio"/> A 8522
10 Minutes Under the glove compartment	

RENAULT	
Clio IV [BH], Captur [J5]	<input type="radio"/> M 5011 <input checked="" type="radio"/> R 5031 <input checked="" type="radio"/> A 8540
10 Minutes Under the glove compartment	
Clio II [BB/CB/SB], Thalia	<input type="radio"/> M 2039 <input checked="" type="radio"/> R 2197 <input checked="" type="radio"/> A 8526
10 Minutes Engine compartment	
Megane III [KZ] Grandtour, Megane III [DZ] Coupe, Megane III [EZ] CC	<input checked="" type="radio"/> R 2327 <input checked="" type="radio"/> A 8534
10 Minutes Engine compartment	
Kangoo II [FW/KW]	<input type="radio"/> M 2078 <input checked="" type="radio"/> A 8553
30 Minutes In the glove compartment	
Espace V [JR]	<input type="radio"/> M 5057 <input checked="" type="radio"/> R 5562 <input checked="" type="radio"/> A 8546
10 Minutes In the glove compartment	
Fluence [L3], Megane III [BZ] Hatchback	<input type="radio"/> M 2247 <input checked="" type="radio"/> R 5574
25 Minutes Under the glove compartment	
Megane II Grandtour, Megane II Hatchback, Megane II Cabrio, Megane II	<input type="radio"/> M 2093 <input checked="" type="radio"/> R 2393
5 Minutes Under the glove compartment	
Traffic II [EL/FL/JL]	<input type="radio"/> M 2208
10 Minutes Engine compartment	
SKODA	
Octavia [5E5] Combi	<input type="radio"/> M 2540 <input checked="" type="radio"/> R 2543 <input checked="" type="radio"/> A 8530
10 Minutes In the glove compartment	
SMART	
Fortwo [451] Cabrio, Fortwo [451] Coupe, Fortwo [453] Coupe, Fortwo [453] Cabrio	<input type="radio"/> M 2299 <input checked="" type="radio"/> R 2499
15 Minutes Driver footwell	
SUBARU	
Legacy [BP] Outback	<input type="radio"/> M 2085 <input checked="" type="radio"/> R 2320
15 Minutes Under the glove compartment	
SUZUKI	
Swift [MZ/EZ] Hatchback, SX4 Hatchback, Swift [AZG] Hatchback	<input type="radio"/> M 2173 <input checked="" type="radio"/> R 5526
10 Minutes Engine compartment	
Jimny [FJ]	<input type="radio"/> M 5088
10 Minutes Beside the glove compartment	
TOYOTA	
Aygo [B1]	<input type="radio"/> M 2189 <input checked="" type="radio"/> A 8552
5 Minutes In the glove compartment	
Corolla [E17], RAV4 [A4], Yaris [P9, VNK], RAV4 [A3], Yaris [P9, JTD]	<input type="radio"/> M 2190 <input checked="" type="radio"/> R 5557 <input checked="" type="radio"/> A 8523
10 Minutes Under the glove compartment	
Yaris [P1], Prius [W20], Celica [T23]	<input type="radio"/> M 2085 <input checked="" type="radio"/> R 2320
15 Minutes Under the glove compartment	
C-HR [X1], Hilux [N12], Hilux [N13]	<input type="radio"/> M 5108 <input checked="" type="radio"/> R 5590
10 Minutes Under the glove compartment	
VOLKSWAGEN	
Golf VI [5K1], Caddy [2C], Golf V [1K1], Golf VI [AJ5] Variant, Caddy [2K]	<input type="radio"/> M 2097 <input checked="" type="radio"/> R 2397 <input checked="" type="radio"/> A 8515
10 Minutes Under the glove compartment	
Touran [5T1]	<input type="radio"/> M 2540 <input checked="" type="radio"/> R 2543 <input checked="" type="radio"/> A 8530
10 Minutes In the glove compartment	
Golf IV [1J1], Golf IV [1J5] Variant	<input checked="" type="radio"/> R 2300 <input checked="" type="radio"/> A 8509
20 Minutes Under the glove compartment	
Passat [3B5] Variant, Passat [3B2]	<input type="radio"/> M 2017 <input checked="" type="radio"/> R 2317
10 Minutes Engine compartment	
Polo [6C1], Polo [614] Sedan, Polo [6R1], Polo [9N1], Polo [612] Sedan	<input type="radio"/> M 5002 <input checked="" type="radio"/> R 5502 <input checked="" type="radio"/> A 8539
10 Minutes Under the glove compartment	
Transporter T5 [7E], Touareg [7LA], Transporter T5 [7J]	<input type="radio"/> M 2114 <input checked="" type="radio"/> R 2431 <input checked="" type="radio"/> A 8517
15 Minutes Under the glove compartment	
Transporter T4 [70, 7D]	<input type="radio"/> M 2056
15 Minutes Under the glove compartment	